




2 - LITER DRINK BOTTLES AND FEEDER




ON BOTH SIDES OF BOTTLE

- CUT ON LINE
- DRILL HOLE THRU
- PUNCH HOLE IN FLAP

- DRILL HOLE THRU CENTER OF CAP

- PUNCH 4-6 SMALL HOLES IN BOTTOM TO DRAIN WATER



- PLACE NYLON OR RPLY AND CORD THRU HOLE PUNCHED ON FLAP AND RAISE BOTH FLAPS SEPARATE TO NECK OF BOTTLE

- PUSH 1/2" DOWEL THRU BOTH HOLES ON BOTTOM FOR PRESS

- PLACE CORD THRU HOLE ON CAP; TIE A SMALL WADDER TO INSIDE OF CAP TO HOLD CORD; REPLACE CAP

- TIE CORD IN LOOP TO HANG ON TREE OR POST